Countersink - Data Sheet





20

40

65

Best Practice Advice

80 mm

GUIDELINE PARAMETERS ONLY - Actual parameters may vary depending on operating conditions

100

55

45

75

1	Follow guidelines to set correct RPM speed. Incorrect RPM can lead to poor life or tool breakage	6	Ensure a debris free surface of sufficient steel thickness for strong magnet hold when Magnet Drilling.
2	Apply firm, steady feed pressure throughout the cut	7	Use at highest available Gear setting (for maximum torque) and use electronic tachometer to set RPM at recommended speed (or slower for difficult applications)
90°	Avoid lateral movement or tilting which can cause damage to the tool	8	Best countersinking results are achieved using a variable speed drill that allows the correct speed to be set. Use at correct RPM (if unsure use tachometer to check drill speed)
4	Ensure regular application of quality cooling lubricant, especially when drilling thick or hardened materials.	9	Piloted Countersink Bits (like the MultiSink) will significantly increase countersinking performance preventing movement of the countersink whilst drilling.
5	Hardened or heat-affected materials may require higher torque, reduced RPM and feed rates and extra coolant		

Quick Guide

1	Optimum life and performance when used with rotary pistol drills or drill presses	
2	Up to 16.5mm can be used on impact wrench & impact drivers for fast cutting performance	
3	Suitable for harder materials such as stainless steel when used at reduced RPM	
4	Use appropriate lubrication and correct RPM to achieve long tool life	